

PROPERTY LOCATED AT: 59 Cedar Ln, Gouldsboro, ME 04607-3339

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I – WATER SUPPLY

TYPE OF SYSTEM: Public Private Seasonal _____ Unknown
 Drilled Dug Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?

Pump (if any): N/A Yes No Unknown
Quantity: Yes No Unknown
Quality: Yes No Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? Yes No
If Yes, Date of most recent test: _____ Are test results available? .. Yes No
To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? Yes No
If Yes, are test results available? Yes No
What steps were taken to remedy the problem? NA

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: 100 feet Northwest of house

Installed by: Unknown

Date of Installation: unknown

USE: Number of persons currently using system: 2

Does system supply water for more than one household? Yes No Unknown

Comments: None

Source of Section I information: Sellers

Buyer Initials _____ Page 1 of 7 Seller Initials TW EW

PROPERTY LOCATED AT: **59 Cedar Ln, Gouldsboro, ME 04607-3339**

SECTION II – WASTE WATER DISPOSAL

TYPE OF SYSTEM: Public Private Quasi-Public _____ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):

Have you had the sewer line inspected?..... Yes No

If Yes, what results: **NA**

Have you experienced any problems such as line or other malfunctions? Yes No

What steps were taken to remedy the problem? **None**

IF PRIVATE (Strike Section if Not Applicable):

Tank: Septic Tank Holding Tank Cesspool Other: _____

Tank Size: 500 Gallon 1000 Gallon Unknown Other: _____

Tank Type: Concrete Metal Unknown Other: _____

Location: **East of the house** OR Unknown

Date installed: **1974** Date last pumped: _____ Name of pumping company: _____

Have you experienced any malfunctions? Yes No

If Yes, give the date and describe the problem: **NA**

Date of last servicing of tank: **Oct 2019** Name of company servicing tank: **Haslam Septic Services**

Leach Field: Yes No Unknown

If Yes, Location: **East of the house**

Date of installation of leach field: **1974** Installed by: **Unkown**

Date of last servicing of leach field: **07/15/2020** Company servicing leach field: **N/A**

Have you experienced any malfunctions? Yes No

If Yes, give the date and describe the problem and what steps were taken to remedy: **NA**

Do you have records of the design indicating the # of bedrooms the system was designed for? Yes No

If Yes, are they available? Yes No

Is System located in a Shoreland Zone? Yes No Unknown

Comments: **None**

Source of Section II information: **Seller**

Buyer Initials _____

Seller Initials  

PROPERTY LOCATED AT: **59 Cedar Ln, Gouldsboro, ME 04607-3339**

SECTION III – HEATING SYSTEM(S)/HEATING SOURCES(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S)	Propane Boiler	Solar collector		
Age of system(s) or source(s)	2018	2008		
Name of company that services system(s) or source(s)	Ray's plumbing	No servicing required		
Date of most recent service call	Fall 2019	na		
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)				
Malfunction per system(s) or source(s) within past 2 years	NO			
Other pertinent information				

Are there fuel supply lines? Yes No Unknown
 Are any buried? Yes No Unknown
 Are all sleeved? Yes No Unknown
 Chimney(s): Yes No
 If Yes, are they lined: Yes No Unknown
 Is more than one heat source vented through one flue? Yes No Unknown
 Had a chimney fire: Yes No Unknown
 Has chimney(s) been inspected? Yes No Unknown
 If Yes, date: **Fall 2019**
 Date chimney(s) last cleaned: **2018**
 Direct/Power Vent(s): Yes No Unknown
 Has vent(s) been inspected? Yes No Unknown
 If Yes, date: **na**

Comments: **none**
 Source of Section III information: **Sellers**

SECTION IV – HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? Yes No Unknown
 If Yes, are tanks in current use? Yes No Unknown
 If no longer in use, how long have they been out of service? **NA**
 If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No Unknown
 Are tanks registered with DEP? Yes No Unknown
 Age of tank(s): **NA** Size of tank(s): **NA**
 Location: **NA**

Buyer Initials _____ Page 3 of 7 Seller Initials DS ELW

PROPERTY LOCATED AT: **59 Cedar Ln, Gouldsboro, ME 04607-3339**

What materials are, or were, stored in the tank(s)? **No Tanks**

Have you experienced any problems such as leakage: Yes No Unknown

Comments: **No Tanks**

Source of information: **Sellers**

B. ASBESTOS — Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work? Yes No Unknown

In the ceilings? Yes No Unknown

In the siding? Yes No Unknown

In the roofing shingles? Yes No Unknown

In flooring tiles? Yes No Unknown

Other: **none** Yes No Unknown

Comments: **None**

Source of information: **Sellers**

C. RADON/AIR - Current or previously existing:

Has the property been tested? Yes No Unknown

If Yes: Date: **na** By: **na**

Results: **NA**

If applicable, what remedial steps were taken? **none**

Has the property been tested since remedial steps? Yes No Unknown

Are test results available? Yes No

Results/Comments: **none**

Source of information: **Seller**

D. RADON/WATER - Current or previously existing:

Has the property been tested? Yes No Unknown

If Yes: Date: **na** By: **na**

Results: **na**

If applicable, what remedial steps were taken? **na**

Has the property been tested since remedial steps? Yes No Unknown

Are test results available? Yes No

Results/Comments: **none**

Source of information: **Sellers**

E. METHAMPHETAMINE - Current or previously existing:

Yes No Unknown

Comments: **NA**

Source of information: **Sellers**

Buyer Initials _____

Seller Initials  

PROPERTY LOCATED AT: **59 Cedar Ln, Gouldsboro, ME 04607-3339**

F. LEAD-BASED PAINT/PAINT HAZARDS — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
..... Yes No Unknown Unknown (but possible due to age)

If Yes, describe location and basis for determination: NA

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: Yes No

If Yes, describe: NA

Are you aware of any cracking, peeling or flaking paint? Yes No

Comments: None

Source of information: Sellers

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: Yes No Unknown

LAND FILL: Yes No Unknown

RADIOACTIVE MATERIAL: Yes No Unknown

Other: None

Source of information: Sellers

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V — GENERAL INFORMATION

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? Yes No Unknown

If Yes, explain: None

Source of information: Sellers

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? Yes No Unknown

If No, who is responsible for maintenance? NA

Road Association Name (if known): NA

Buyer Initials _____

Seller Initials  

PROPERTY LOCATED AT: **59 Cedar Ln, Gouldsboro, ME 04607-3339**

Are there any tax exemptions or reductions for this property for any reason including but not limited to: Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
..... Yes No Unknown

If Yes, explain: **Homestead**

Is a Forest Management and Harvest Plan available?..... Yes No Unknown
Is house now covered by flood insurance policy (not a determination of flood zone) Yes No Unknown
Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water filtration system, photovoltaics, wind turbines): Type: **Propane tank**

Year Principal Structure Built: **1975**
What year did Seller acquire property? **2004**
Roof: Year Shingles/Other Installed: **2005**

Water, moisture or leakage: **no**
Comments: **Standing seam metal roof**

Foundation/Basement:

Is there a Sump Pump? Yes No Unknown
Water, moisture or leakage since you owned the property: Yes No Unknown
Prior water, moisture or leakage? Yes No Unknown
Comments: **none**

Mold: Has the property ever been tested for mold? Yes No Unknown
If Yes, are test results available? Yes No



Electrical: Fuses Circuit Breaker Other: **Generator and solar panels** Unknown
Has all or a portion of the property been surveyed? Yes No Unknown
If Yes, is the survey available? Yes No Unknown

Manufactured Housing – Is the residence a:

Mobile Home Yes No Unknown
Modular Yes No Unknown

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may have an adverse impact on health/safety: **none**

Source of Section V information: **Sellers**

Buyer Initials _____ Page 6 of 7 Seller Initials  

PROPERTY LOCATED AT: **59 Cedar Ln, Gouldsboro, ME 04607-3339**

SECTION VI – ADDITIONAL INFORMATION

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: Yes No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

DocuSigned by:
Thomas Walsh 7/16/2020
SELLER DATE
Thomas Walsh

DocuSigned by:
Elizabeth Walsh 7/16/2020
SELLER DATE
Elizabeth Walsh

SELLER DATE

SELLER DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER DATE

BUYER DATE

BUYER DATE

BUYER DATE